



BOSTON COLLEGE

UNIT INSPECTION - ROOM #125

LOCATION:

Boston
College
Campus, 217
College Hill
Drive.

TENANT:

John Smith

MOVE IN:

23/2/16

STUDENT ID:

08045523

INSPECTION

DATE:

12/12/2012

LIVING AREA

Details	Clean	Undamaged	Working	Action Required	Comments
Wall/Cladding	✗			Y	Clean and in good condition
Room Door		✓	✓	Y	
Closet Door	✓	✓	✓	N	
Window	✓	✗	✓	Y	
Window Screens	✓	✓	✓		
Blinds	✓	✗	✓		

KITCHEN

Details	Clean	Undamaged	Working	Action Required	Comments
Wall/Cladding	✓	✓	✗	Y	
Room Door	✓	✓	✓	Y	
Closet Door	✗	✓	✓	N	

Details	Clean	Undamaged	Working	Action Required	Comments
Window	✓	✗	✓	Y	
Window Screens	✓	✓	✗		
Blinds	✗	✓	✓		

GENERAL COMMENTS

Room is in great condition. Overall kept clean and tidy. Tenant will need to address issues that have been highlighted in the report.

SIGNATURES

Tenant:

PHOTOS TAKEN

